

HPC 20-83


8049, 8055, 8059, 8061 (Tiber Park) and 8069 Main Street; Vicinity of Maryland Avenue and Main Street; Vicinity of 3711 Maryland Avenue along Patapsco River, Ellicott City

Photos / Documentation of Stream Channel Walls

Prepared by Howard County Department of Public Works

10 February 2021

19 Pages Total



Aerial view keyed to photos
Not to Scale



Notes:

- Squared / Coursed
- Hand split, markings visible
- Minimal mortar joints
- Very large stones
- *This section of wall to remain

Image 1 - 8049 Main Street - North Wall

*Black and white intensity setting used as area is very dark



- Notes:
- Roughly coursed, roughly squared
 - Some tool markings visible from wedge splitting process
 - Minimal mortar joints

Image 2 - 8049 Main Street - South Wall

*Black and white intensity setting used as area is very dark



Notes:

- Roughly squared, uncoursed
- Large stones

*This section of wall to remain

Image 3 - 8055 Main Street - North Wall

*Black and white intensity setting used as area is very dark



Image 4 - 8055 Main Street - South Wall

*Black and white intensity setting used as area is very dark

- Notes:
- Roughly coursed, irregular shaped stones
 - Several types/patterns of mortar visible




Image 5a - 8059 Main Street - North Wall

Notes:
- Uncoursed rubble with squared stones above
*This section of wall to remain



Image 5b - 8059 Main Street - North Wall

*Black and white intensity setting. Same view as Image 5a.

Notes:
- Uncoursed rubble with squared stones above
*This section of wall to remain



- Notes:
- Roughly coursed, roughly squared
 - Some tool markings visible from wedge splitting process
 - Wider mortar joints

Image 6a - 8059 Main Street - South Wall



Notes:

- Roughly coursed, roughly squared
- Some tool markings visible from wedge splitting process
- Wider mortar joints

Image 6b - 8059 Main Street - South Wall

*Black and white intensity setting. Same view as Image 6a.



- Notes:
- Highly coursed, roughly squared
 - Some tool markings visible from wedge splitting process
 - Minimal mortar joints

Image 7a - 8061 Main Street (Tiber Park) - North Wall



Notes:

- Highly coursed, roughly squared
- Some tool markings visible from wedge splitting process
- Minimal mortar joints

Image 7b - 8061 Main Street (Tiber Park) - North Wall

*Black and white intensity setting. Same view as Image 7a.



- Notes:
- Highly coursed, squared
 - Some tool markings visible from wedge splitting process
 - Larger stones than North wall in this area
 - Minimal mortar joints

Image 8a - 8061 Main Street (Tiber Park) - South Wall



Notes:

- Highly coursed, squared
- Some tool markings visible from wedge splitting process
- Larger stones than North wall in this area
- Minimal mortar joints

Image 8b - 8061 Main Street (Tiber Park) - South Wall

*Black and white intensity setting. Same view as Image 8a.



Notes:

- Uncoursed rubble
- Some tool markings visible from wedge splitting process
- Minimal mortar joints

Image 9a - 8069 Main Street - North Wall



Notes:

- Uncoursed rubble
- Some tool markings visible from wedge splitting process
- Minimal mortar joints

Image 9b - 8069 Main Street - North Wall

*Black and white intensity setting. Same view as Image 9a.



- Notes:
- Uncoursed rubble
 - Some tool markings visible from wedge splitting process
 - Minimal mortar joints

Image 10 - 8069 Main Street - North Wall



Image 11a - 8069 Main Street - South Wall

*Black and white intensity setting. RGB view was very dark.

Notes:

- Uncoursed rubble
- Some tool markings visible from wedge splitting process
- Minimal mortar joints



Notes:

- Uncoursed rubble
- Some tool markings visible from wedge splitting process
- Minimal mortar joints

Image 11b - 8069 Main Street - South Wall