## Robert Fulton Drive

Columbia Gateway Drive to Lee Deforest Drive—Looking towards Columbia Gateway Drive




**Existing Condition (64' Existing Total Width)** 




Option 1A / 1C / 1D: South Side of Roadway (69' Proposed Total Width)

Convert existing sidewalk to shared-use path



Option 1B: North Side of Roadway (77' - 79' Proposed Total Width)\*

Existing sidewalk remains (south side), new shared-use path with 5' buffer (north side)




Example: Shared-Use Path (Columbia, MD)

\*Note: Path width varies between 8' - 10' for this option to minimize impacts to existing natural resources.








**Existing Condition (98' Existing Total Width)** 



Option 1A: South Side of Roadway (106' - 108' Proposed Total Width)\*

Convert existing sidewalk to shared-use path with 5' buffer



Option 1B: North Side of Roadway (111' - 113' Proposed Total Width)\*


Existing sidewalk remains (south side), new shared-use path with 5' buffer (north side)



Option 1C: Reduce Median and Adjust Curb (98' Proposed Total Width)

Convert existing sidewalk to shared-use path with 5' buffer

\*Note: Path width varies between 8' - 10' for this option to minimize impacts to existing natural resources.



Example: Shared-Use Path (Columbia, MD)

Howard County, Maryland

