

# Little Patuxent Watershed Howard County, Maryland





Figure 1




Figure 2: Little Patuxent Watershed  
Digital Orthophoto Quarter Quad 1993

0.5 0 0.5 1 Miles

1:60,000






Figure 3: Little Patuxent Watershed  
USGS 7.5 Minute Topographic Map

0.5 0 0.5 1 Miles

1:60,000



# Pipe Outfalls A




Figure 4a: Map of Upper Little Patuxent Watershed Pipe Outfalls

# Pipe Outfalls B




Figure 4b: Map of Lower Little Patuxent Watershed Pipe Outfalls

# Tree Blockages




Figure 5: Map of Little Patuxent Watershed Tree Blockages

# Erosion




Figure 6a: Map of Little Patuxent Watershed Erosion Sites

# Inadequate Buffer





Figure 7a: Map of Little Patuxent Watershed Inadequate Buffer Sites



# Fish Migration Barriers



- Severity
- # Very Severe
  - Severe
  - 3 Moderate
  - + Low\_Severity
  - z Minor

Streams

Roads

Little\_Patuxent\_Watershed

0.5 0 0.5 1 Miles

1:60,000



Figure 8a: Map of Little Patuxent Watershed Fish Migration Barrier Sites

# Channel Alteration




Figure 9a: Map of Little Patuxent Watershed Channel Alteration Sites

# Exposed Pipe




Figure 10a: Map of Little Patuxent Watershed Exposed Pipe Sites

# Unusual Condition/Comment




Figure 11a: Map of Little Patuxent Watershed Unusual Condition/Comment Sites

# Trash Dumping




Figure 12a: Map of Little Patuxent Watershed Trash Dumping Sites

# In Stream Construction




Figure 13: Map of Little Patuxent Watershed In Stream Construction Sites

# Representative Sites




Figure 14: Little Patuxent Watershed Representative Sites

# Pond Sites




Figure 15: Map of Little Patuxent Watershed Pond Sites